OCEAN OPTICS UV/VIS SPECTROMETERS <u>INSTRUCTIONS FOR START-UP/SHUT DOWN</u> Mac Computers

Updated November 14, 2017
Celeste Morin, x3756, Druckenmiller 243

1) Plug the power cable into the wall. The spectrometer fan may turn on at this point. If not, it will turn on in Step #2.
2) Plug the USB cable into the spectrometer and back of computer. Fan should be on at this point, if not see your lab instructor.
3) Open the Logger Pro software. You should hear a "click" sound when logging in and out of the software. Communication has been established.
4) When finished using the spectrometer, unplug the power cable from the wall and unplug the USB cable from the spectrometer. Use the "apple/Q" command to quit out of the Logger Pro software.
5) The next set of students must perform Steps 1 through 4.

Created by: Celeste Morin